

## ROUTING AND RECORD SHEET

SUBJECT: (Optional)  
Halon 1301 Fire Suppression System for the Raised Floor Space in the  
Computer and Communications Equipment Rooms, New Headquarters Addition

FROM: [Redacted]  
Chief, Safety Staff, DDA  
[Redacted]

EXTENSION

NO.

DATE 19 June 1984

TO: (Officer designation, room number, and building)

DATE

RECEIVED

FORWARDED

OFFICER'S INITIALS

COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.)

1. C/NBPO/OL  
3E40 Hqs.

2.

3.

4.

5.

6.

7.

8.

9.

10.

11.

12.

13.

14.

15.

Larry  
Paul  
Pam  
Jerry  
Gary  
Joe  
Imo

Art: Route - Cy  
cys to:

OL Road 25 June

Forward - Toss

File:

SAFETY

20 JUN 1984

MEMORANDUM FOR: Chief, New Building Planning Office,  
Office of Logistics

STAT FROM:

Chief, Safety Staff, DDA

SUBJECT: Halon 1301 Fire Suppression System for the  
Raised Floor Space in the Computer and  
Communications Equipment Rooms,  
New Headquarters Addition

REFERENCE: Memo for C/BPS/OL from C/SS/DDA  
dated 31 May 1983. Subject: Fire Protection  
for Computer Room Raised Floor Space in the  
Planned Addition to Headquarters Building

1. Efforts to provide a Halon 1301 fire suppression system for the raised floor space in the communications and computer equipment areas in the Headquarters Addition Project have not been successful. The Safety Staff believes that the lack of these systems will expose these facilities to an unacceptable risk and recommends that the issue be reconsidered.

2. A fire suppression system for the indicated spaces was not incorporated into the building design project because of the lack of enforcing criteria. In recognition that the fire protection for these spaces may be deficient, the Safety Staff fire protection engineer prepared the reference Memorandum which compared fire protection criteria for similar installations. Criteria investigated consisted of the following:

- a. GSA Handbook of Building Fire Safety Criteria.
- b. Department of Commerce, RP-1, "Standard Practice for the Fire Protection of Essential Electronic Equipment Operations".
- c. NAVFAC DM-8, Naval Facilities Engineering Command, Fire Protection Engineering Design Manual.
- d. Department of Defense Construction Criteria Manual, DOD 4270.1-M.

OL 20291-84

e. Final draft of the proposed Tri-Service Fire Protection Engineering Manual for the Departments of the Army, Navy and Air Force.

It was found that the Department of Defense Manual requires underfloor fire suppression for all electronic equipment areas. NAVFAC DM-8 and the DOD Tri-Service Manual require an underfloor fire suppression system if the volume of the raised floor space exceeds 2,000 cubic feet. The Department of Commerce RP-1 Manual requires underfloor protection if the height of the raised floor is 18 inches or higher. The GSA Handbook, does not specifically address the subject of raised floor space protection.

3. The New Building Project has utilized GSA criteria for design of the building. The GSA Fire Protection Handbook acknowledges that it "does not provide detailed guidelines for safeguarding special valuable, important or critical operations or equipment that does not present a particular fire risk. Limited fire damage up to the destruction of the contents of the room or area of origin, radiant heat damage to nearby areas, and smoke damage extending for a considerable distance from the point of fire origin is normally accepted. In situations where this level of damage cannot be accepted, additional safeguards may be necessary to protect against damage from adjacent or nearby operations....Each situation must be individually considered and evaluated against the potential exposures." Conversely, the criteria set forth by DOD and military criteria recognizes the need to protect computer areas where strategically important or mission essential functions are conducted and continued operation of equipment is essential to ongoing operations.

4. An uncontrolled fire in the raised floor space of a communications center or computer room would result in complete destruction of the area despite the overhead sprinkler system. With the assumption that an event such as this cannot be tolerated, the Safety Staff highly recommends the installation of raised floor fire suppression systems for these areas. This action would parallel Military and DOD regulations and would provide an acceptable level of fire protection. The cost of the systems for the initial 120,000 square feet of electronic equipment area is approximately 100,000 dollars as shown on the attachment.

5. If there are any questions, or if additional information is required, please contact the Safety Staff on extension

STAT

STAT

Attachment



2011

MEMORANDUM FOR: Chief, Building Planning Staff  
Office of Logistics

STAT

FROM:

Chief, Safety Staff, DDA

SUBJECT: Fire Protection for Computer Room Raised Floor  
Space in the Planned Addition to Headquarters  
Building

REFERENCE: Memo for C/SS/DDA from C/BPS, Subject: Planned  
Addition to Headquarters Building, Dated  
17 May 1983.

1. Reference paragraph 1(c) stated that a Halon 1301 fire extinguishing system will not be specified for computer room protection in accordance with GSA policy.

2. The Safety Staff strongly recommends that a Halon 1301 fire extinguishing system should be provided for the raised floor space in the computer rooms. An investigation of applicable codes, criteria, and related documents was performed and the findings support the need for raised floor plenum protection.

a. The GSA Handbook of Building Fire Safety Criteria states "Halon 1301 extinguishing systems shall not be used as a substitute for automatic sprinkler protection in GSA installations; however, GSA may elect to augment automatic sprinklers with Halon 1301 protection." (Chapt 5-5b). This indicates that Halon may not be used to provide total room fire protection. However, the area of concern is the space below the raised floor which contains the cables for the computer equipment. The overhead sprinkler system would be ineffective for a fire originating within this space.

b. Chapter 6-4 of the Fire Safety Criteria Handbook addresses fire protection for electrical conductors in plenums, ceilings, voids and similar spaces. It indicates that plenum spaces with non plenum rated conductors shall be provided with automatic sprinkler protection or the conductors shall be installed in conduit. This includes all telephone, signal and equipment wires. Experience shows that installing all wire and cable in conduit is not practical because of the transitory nature of computer facilities.

c. The GSA Handbook acknowledges that "This handbook does not provide detailed guidelines for safeguarding special valuable, important or critical operations or equipment that does not present a particular fire risk. Limited fire damage up to the destruction of the contents of the room or area of origin, radiant heat damage to nearby areas, and smoke damage extending for a considerable distance from the point of fire origin is normally accepted. In situations where this level of damage cannot be accepted, additional safeguards may be necessary to protect against damage from adjacent or nearby operations....Each situation must be individually considered and evaluated against the potential exposures". (Chapt 7-13).

d. In addition to the requirements stated in the GSA Handbook, Chapter 7-5 indicates that fire protection for electronic equipment shall conform to the National Fire Prevention and Control Administrations issue of RP-1, "Standard Practice for the Fire Protection of Essential Electronic Equipment Operations".

e. RP-1 indicates that Halon 1301 fire extinguishing systems may be considered in electronic equipment areas where there is a critical need to protect data in process, a desire to reduce equipment fire damage through early automatic fire extinguishment, a need to protect void spaces not suitable for sprinkler protection (i.e., beneath the raised floor), or a critical need to facilitate return to service. Section 707 of RP-1 addresses the protection requirements for raised floor areas. It notes that the space under the raised floor presents a significant hazard to the electronic equipment and warrants separate consideration. The criteria set forth by RP-1 for raised floor area protection is based upon the vertical distance between the raised floor and the supporting slab. For a depth of 18 inches or less, Halon protection is optional. For a depth of 18 inches to 36 inches, Halon protection or automatic sprinkler protection must be provided. A depth greater than 36 inches requires automatic sprinkler protection. It is the opinion of the Safety Staff Fire Protection Engineer that the depth criteria is unsound. Progressive criteria for determining the need for Halon protection is based upon the value of the equipment, the strategic importance of the equipment, the volume of the under floor area, the use of the under floor area as a plenum and the replacement time of the computer equipment.

f. The Department of Defense Construction Criteria Manual 4270.1M and the Department of the Navy Design Manual DM-8, Fire Protection Engineering, specify protection requirements for raised floor areas in military computer installations. Their criteria requires all raised floor spaces to be protected by a Halon or carbon dioxide fire extinguishing system unless the value of the equipment is less than \$500,000 or the volume of the space is less than 2000 cu. ft.

3. Aside from the combustibles located within the computer room, the raised floor space is the most probable source of a fire. This is attributed to the power cables enclosed within the space. A fire originating in this area presents a unique fire extinguishing problem as explained below.

a. The actual location of the fire may not be pinpointed because of the high air flow in the raised floor space. Smoke from the fire would be forced away from the point of origin. The smoke detector that actuates may be remote from the actual location of the fire.

b. The air flow under the raised floor is usually so high it accelerates the spread of the fire. In addition, the velocity of the air flow inhibits the ability of the smoke detector to actuate. In order to combat this effect, the spacing of the detectors is reduced from 900 sq. ft. per detector to 125 sq. ft. per detector. However, the detection capability of the detection system has been reduced. This may result in delayed detection creating the potential for a fire of a magnitude that could not be manually extinguished by the occupants.

c. The significant amount of electrical equipment, work stations and storage racks located on the raised floor limit accessibility to the space below. This hampers efforts to locate the fire and effect extinguishment.

d. The noxious fumes produced by the burning cable insulation would hamper extinguishing efforts by the computer room occupants. A minimal amount of smoke would be sufficient for rendering the area untenable.

e. The amount of heat and smoke generated by the fire could be significant before the fire is located and extinguished. The smoke itself has the capability of severely damaging equipment and tapes due to the corrosive nature of the particulates.



f. An uncontrolled fire in the raised floor space would destroy the computer facility and could injure those occupants trying to suppress the fire.

4. A Halon system for the raised floor space would extinguish a fire involving cabling, power supplies or other combustibles. A benefit of the system is that it also provides protection for the computer equipment. Most computers will draw air from the raised floor space for internal cooling. As a result, the Halon gas is also drawn into the computer which would extinguish an internal fire.

5. GSA criteria requires an extinguishing system for plenums containing cabling and wire not in conduit. In addition, NFPA No. 13, Installation of Sprinkler Systems, requires combustible concealed spaces to be provided with sprinkler protection. Omission of the Halon system would require the installation of sprinklers in the raised floor space. In recognition that the GSA criteria does not address protection requirements for special important installations of a vital nature, the criteria set forth by DOD and the Department of the Navy should be followed. The function of the Agency computer areas parallel the importance of DOD installations. The protection provided for our installations should parallel theirs.

6. It should be recognized that the criteria referenced is the minimal acceptable criteria and not a design guide. This criteria is based upon previous fire and loss experience in computer installations. To provide a level of protection that is considered minimal could not be determined to be in the best interests of the Agency. The risk assumed by not providing a Halon system is considered excessive when compared to the protection gained by installing the system. If only used once, the system has more than paid for itself in equipment saved, minimized down time and records protected.

7. If there are any additional questions, please contact the Safety Staff on extension

STAT

Distribution:

Original - Addressee

① - Subject

- Chrono

STAT

SS/DDA:  :jw(27 May 1983)

STAT.

Approved For Release 2009/03/20 : CIA-RDP89-00244R000701410009-5

NAVFAC 11013/7 (1-78) Supersedes NAVDOCKS 2417 and 2417A		COST ESTIMATE		DATE PREPARED 5-8-84		SHEET 1 OF 2	
ACTIVITY AND LOCATION HALON SYSTEM TO PROTECT TWO- 15,000 # RAISED FLOOR AREAS W/18" DEPTH PROJECT TITLE NEW HEADQUARTERS BUILDING ADDITION		CONSTRUCTION CONTRACT NO.		STATUS OF DESIGN <input type="checkbox"/> PED <input type="checkbox"/> 30% <input type="checkbox"/> 100% <input type="checkbox"/> FINAL <input type="checkbox"/> Other (Specify)		IDENTIFICATION NUMBER CATEGORY CODE NUMBER JOB ORDER NUMBER	
ITEM DESCRIPTION	QUANTITY		MATERIAL COST		LABOR COST		ENGINEERING ESTIMATE
	NUMBER	UNIT	UNIT COST	TOTAL	UNIT COST	TOTAL	TOTAL
HALON SYSTEM (30,000 # COVERAGE)							
350 # HALON STORAGE CYLINDER	2	EA	1730	3460	375	750	4210
BOTTLE STRAPS	2	EA	18	36			36
SOLENOID VALVE ASSEMBLY	2	EA	100	200			200
SELECTOR VALVE	2	EA	1340	2680			2680
2" CHECK VALVE	2	EA	266	532			532
2" FLEX BEND	2	EA	144	288			288
PRESSURE SWITCH	2	EA	116	232			232
CONNECTING CHANNEL	1	EA	26	26	X	X	26
1" BRASS NOZZLE	6	EA	26.5	159	2.50	15	174
1" SCH. 80 BLACK STEEL PIPE	60	FT	2.75	165	1.85	51	216
1 1/4" SCH. 80 BLACK STEEL PIPE	60	FT	3.40	204	1.05	63	267
1 1/2" SCH. 80 BLACK STEEL PIPE	90	FT	3.80	342	1.10	99	441
HALON 1301 GAS	660	LBS	8.80	5808	-		5808
HALON 122 TEST GAS	660	LBS	4.80	3168	-		3168
TESTING					480	480	480
(cont)							

NAVJAC 1013/7 (1-7U)  
Superseries NAVDOCKS 2417 and 2417A

## DATE PREPARED:

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100  
101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141  
142  
143  
144  
145  
146  
147  
148  
149  
150  
151  
152  
153  
154  
155  
156  
157  
158  
159  
160  
161  
162  
163  
164  
165  
166  
167  
168  
169  
170  
171  
172  
173  
174  
175  
176  
177  
178  
179  
180  
181  
182  
183  
184  
185  
186  
187  
188  
189  
190  
191  
192  
193  
194  
195  
196  
197  
198  
199  
200  
201  
202  
203  
204  
205  
206  
207  
208  
209  
210  
211  
212  
213  
214  
215  
216  
217  
218  
219  
220  
221  
222  
223  
224  
225  
226  
227  
228  
229  
230  
231  
232  
233  
234  
235  
236  
237  
238  
239  
240  
241  
242  
243  
244  
245  
246  
247  
248  
249  
250  
251  
252  
253  
254  
255  
256  
257  
258  
259  
260  
261  
262  
263  
264  
265  
266  
267  
268  
269  
270  
271  
272  
273  
274  
275  
276  
277  
278  
279  
280  
281  
282  
283  
284  
285  
286  
287  
288  
289  
290  
291  
292  
293  
294  
295  
296  
297  
298  
299  
300  
301  
302  
303  
304  
305  
306  
307  
308  
309  
310  
311  
312  
313  
314  
315  
316  
317  
318  
319  
320  
321  
322  
323  
324  
325  
326  
327  
328  
329  
330  
331  
332  
333  
334  
335  
336  
337  
338  
339  
340  
341  
342  
343  
344  
345  
346  
347  
348  
349  
350  
351  
352  
353  
354  
355  
356  
357  
358  
359  
360  
361  
362  
363  
364  
365  
366  
367  
368  
369  
370  
371  
372  
373  
374  
375  
376  
377  
378  
379  
380  
381  
382  
383  
384  
385  
386  
387  
388  
389  
390  
391  
392  
393  
394  
395  
396  
397  
398  
399  
400  
401  
402  
403  
404  
405  
406  
407  
408  
409  
410  
411  
412  
413  
414  
415  
416  
417  
418  
419  
420  
421  
422  
423  
424  
425  
426  
427  
428  
429  
430  
431  
432  
433  
434  
435  
436  
437  
438  
439  
440  
441  
442  
443  
444  
445  
446  
447  
448  
449  
450  
451  
452  
453  
454  
455  
456  
457  
458  
459  
460  
461  
462  
463  
464  
465  
466  
467  
468  
469  
470  
471  
472  
473  
474  
475  
476  
477  
478  
479  
480  
481  
482  
483  
484  
485  
486  
487  
488  
489  
490  
491  
492  
493  
494  
495  
496  
497  
498  
499  
500  
501  
502  
503  
504  
505  
506  
507  
508  
509  
510  
511  
512  
513  
514  
515  
516  
517  
518  
519  
520  
521  
522  
523  
524  
525  
526  
527  
528  
529  
530  
531  
532  
533  
534  
535  
536  
537  
538  
539  
540  
541  
542  
543  
544  
545  
546  
547  
548  
549  
550  
551  
552  
553  
554  
555  
556  
557  
558  
559  
560  
561  
562  
563  
564  
565  
566  
567  
568  
569  
570  
571  
572  
573  
574  
575  
576  
577  
578  
579  
580  
581  
582  
583  
584  
585  
586  
587  
588  
589  
590  
591  
592  
593  
594  
595  
596  
597  
598  
599  
600  
601  
602  
603  
604  
605  
606  
607  
608  
609  
610  
611  
612  
613  
614  
615  
616  
617  
618  
619  
620  
621  
622  
623  
624  
625  
626  
627  
628  
629  
630  
631  
632  
633  
634  
635  
636  
637  
638  
639  
640  
641  
642  
643  
644  
645  
646  
647  
648  
649  
650  
651  
652  
653  
654  
655  
656  
657  
658  
659  
660  
661  
662  
663  
664  
665  
666  
667  
668  
669  
670  
671  
672  
673  
674  
675  
676  
677  
678  
679  
680  
681  
682  
683  
684  
685  
686  
687  
688  
689  
690  
691  
692  
693  
694  
695  
696  
697  
698  
699  
700  
701  
702  
703  
704  
705  
706  
707  
708  
709  
710  
711  
712  
713  
714  
715  
716  
717  
718  
719  
720  
721  
722  
723  
724  
725  
726  
727  
728  
729  
730  
731  
732  
733  
734  
735  
736  
737  
738  
739  
740  
741  
742  
743  
744  
745  
746  
747  
748  
749  
750  
751  
752  
753  
754  
755  
756  
757  
758  
759  
760  
761  
762  
763  
764  
765  
766  
767  
768  
769  
770  
771  
772  
773  
774  
775  
776  
777  
778  
779  
780  
781  
782  
783  
784  
785  
786  
787  
788  
789  
790  
791  
792  
793  
794  
795  
796  
797  
798  
799  
800  
801  
802  
803  
804  
805  
806  
807  
808  
809  
810  
811  
812  
813  
814  
815  
816  
817  
818  
819  
820  
821  
822  
823  
824  
825  
826  
827  
828  
829  
830  
831  
832  
833  
834  
835  
836  
837  
838  
839  
840  
84

### ACTIVITY AND LOCATION

CONSTRUCTION CONTRACT NO.

[illegible]

PROJECT TITLE

ESTIMATED BY

CATEGORY CODE NUMBER

### STATUS OF DESIGN

☐ PED ☐ 30% ☐ 100% ☐ FINAL ☐ Other (Specify) \_\_\_\_\_

JOB ORDER NUMBER	
------------------	--

SAY	\$100,000
-----	-----------